



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

**In re application of:** Bogan et al.

**Date Mailed** September 7, 2005

**Patent No.** 6,772,782

**Issued:** August 10, 2004

**Application No.** 10/700,807

**Filed:** November 3, 2003

**Confirmation No.** 6260

**For:** CABLE ROUTING IN WASTEWATER  
LIFT STATION

**Certificate**

**Examiner:** A. Michael Chambers

**SEP 16 2005**

**Art Unit:** 3753

**of Correction**

**Attorney Reference No.** 6397-66880-01

COMMISSIONER FOR PATENTS

P.O. BOX 1450

ALEXANDRIA, VA 22313-1450

LETTER OF CORRECTION

The following printing errors were noted in comparing the printed patent with the papers in the attorneys' files:

In "Other Publications":

Cover sheet, "www.tipton.org/lift station2.html" should read  
--www.tipton.org/lift\_station2.html--.

In the Specification:

Column 10, line 30, "surface of the of the top" should read --surface of the top--.

All of the above errors are not considered to be of major significance. Applicants request that this document be included in the file wrapper of the subject patent to make formal notice of the errors.

PATENT  
Attorney Matter No. 6397-66880-01

Respectfully submitted,

KLARQUIST SPARKMAN, LLP

By   
Ted W. Baker  
Registration No. 53,961

One World Trade Center, Suite 1600  
121 S.W. Salmon Street  
Portland, Oregon 97204  
Telephone: (503) 226-7391  
Facsimile: (503) 228-9446

cc: Client  
Docketing